



## **PRODUCT SAFETY WARNING**

### **Micromark 2 Kilowatt Convector Heaters**

Haringey Trading Standards have learnt that there is a possible fault with some of the above heaters which could cause them to overheat and pose a potential fire risk.

The Model numbers affected are; MM53582, MM53583 and MM53584

This warning only affects these 3 models of heater and only applies to ones from specific batches.

The model and batch numbers are clearly indicated on a label on the rear of the product and were also on the base of the product retail box.

The warning only applies to heaters produced in 2006 which have batch numbers ending :

**0607, 0608, 0609, 0611 or 0612**

If you, or someone you know, owns one of the affected products please;-

Stop using the heater immediately and dispose of it by taking it to one of the Council's recycling centres

**NO OTHER MICROMARK PRODUCT IS AFFECTED BY THIS NOTICE.**

Unfortunately, BDC Limited, the former holders of the 'Micromark' brand who supplied the heaters, are now in liquidation, and so there is no further information.